



**HYTORC VERSA-14
PRESSURE/TORQUE CONVERSION CHART**

PRESSURE IN PSI				PRESSURE IN BAR
	FT. LBS.	KGM	NM	
1500	2153	298	2918	104
1600	2294	317	3110	110
1800	2577	356	3494	124
2000	2861	396	3878	138
2200	3153	436	4274	152
2400	3445	477	4671	165
2600	3738	517	5067	179
2800	4030	557	5463	193
3000	4323	598	5860	207
3200	4624	640	6269	220
3400	4926	681	6678	234
3600	5228	723	7087	248
3800	5530	765	7496	262
4000	5831	806	7905	276
4200	6133	848	8313	290
4400	6434	890	8722	303
4600	6735	931	9130	317
4800	7037	973	9539	331
5000	7338	1015	9947	345
5200	7651	1058	10372	358
5400	7964	1101	10797	372
5600	8278	1145	11221	386
5800	8591	1188	11646	400
6000	8904	1231	12070	414
6200	9199	1272	12471	427
6400	9495	1313	12871	441
6600	9790	1354	13272	455
6800	10086	1395	13672	468
7000	10381	1436	14073	482
7200	10685	1478	14485	496
7400	10989	1520	14896	510
7600	11293	1562	15308	524
7800	11596	1604	15720	538
8000	11900	1646	16132	552
8200	12194	1686	16530	565
8400	12488	1727	16928	579
8600	12782	1768	17327	593
8800	13075	1808	17725	607
9000	13369	1849	18123	620
9200	13694	1894	18563	634
9400	14018	1939	19003	648
9600	14343	1984	19443	662
9800	14667	2029	19883	676
10000	14992	2073	20323	690

12420 TEXACO ROAD Houston, Texas 77013 713-453-6677 www.hyorctexas.com

This chart supercedes all prior version regarding this tool

08/02/2011