



Since 1968

HYTORC VERSA-30
PRESSURE/TORQUE CONVERSION CHART

PRESSURE IN PSI				PRESSURE IN BAR
	FT. LBS.	KGM	NM	
1500	5170		7010	104
1600				110
1800				124
2000	6918		9380	138
2200				152
2400				165
2600				179
2800				193
3000	10547		14300	207
3200				220
3400				234
3600				248
3800				262
4000	14010		18995	276
4200				290
4400				303
4600				317
4800				331
5000	16482		22835	345
5200				358
5400				372
5600				386
5800				400
6000	21245		28804	414
6200				427
6400				441
6600				455
6800				468
7000	24860		33706	482
7200				496
7400				510
7600				524
7800				538
8000	28545		38702	552
8200				565
8400				579
8600				593
8800				607
9000	32167		43613	620
9200				634
9400				648
9600				662
9800				676
10000	35813		48556	690

12420 TEXACO ROAD Houston, Texas 77013 713-453-6677 www.hyorctexas.com

This chart supercedes all prior version regarding this tool

10/01/2013