



Since 1968

HYTORC VERSA-8 SLIM #: 2-3
PRESSURE/TORQUE CONVERSION CHART

PRESSURE IN PSI	PRESSURE/TORQUE CONVERSION CHART			PRESSURE IN BAR
	FT. LBS.	KGM	NM	
1500	1295	179	1756	104
1600	1388	192	1882	110
1800	1573	218	2133	124
2000	1758	243	2384	138
2200	1933	267	2621	152
2400	2109	292	2860	166
2600	2284	316	3097	179
2800	2460	340	3336	193
3000	2635	364	3573	207
3200	2817	390	3820	221
3400	2999	415	4067	235
3600	3181	440	4313	248
3800	3363	465	4560	262
4000	3545	490	4807	276
4200	3722	515	5047	290
4400	3899	539	5287	304
4600	4077	564	5528	317
4800	4254	588	5768	331
5000	4431	613	6008	345
5200	4607	637	6247	359
5400	4783	661	6486	373
5600	4959	686	6724	386
5800	5135	710	6963	400
6000	5311	735	7202	414
6200	5489	759	7443	428
6400	5666	784	7683	442
6600	5844	808	7924	455
6800	6022	833	8166	469
7000	6200	857	8407	483
7200	6380	882	8651	497
7400	6560	907	8895	511
7600	6740	932	9139	524
7800	6920	957	9384	538
8000	7100	982	9628	552
8200	7273	1006	9862	566
8400	7446	1030	10097	580
8600	7618	1054	10330	593
8800	7791	1077	10565	607
9000	7963	1101	10798	621
9200	8140	1126	11038	635
9400	8317	1150	11278	649
9600	8494	1175	11518	662
9800	8671	1199	11758	676
10000	8848	1224	11998	690

12420 TEXACO ROAD Houston, Texas 77013 713-453-6677 www.hyorctexas.com

This chart supercedes all prior version regarding this tool

08/02/2011