



Since 1968

HYTORC VERSA-8 SLIM #: 4-9
PRESSURE/TORQUE CONVERSION CHART

PRESSURE IN				PRESSURE IN
PSI	FT. LBS.	KGM	NM	BAR
1500	1457	202	1976	104
1600	1564	216	2121	110
1800	1779	246	2412	124
2000	1994	276	2704	138
2200	2187	302	2966	152
2400	2381	329	3229	166
2600	2574	356	3490	179
2800	2767	383	3752	193
3000	2960	409	4014	207
3200	3178	440	4309	221
3400	3395	470	4604	235
3600	3613	500	4899	248
3800	3830	530	5193	262
4000	4048	560	5489	276
4200	4235	586	5743	290
4400	4422	612	5996	304
4600	4610	638	6251	317
4800	4797	663	6505	331
5000	4984	689	6758	345
5200	5184	717	7030	359
5400	5383	744	7299	373
5600	5582	772	7569	386
5800	5781	800	7839	400
6000	5980	827	8109	414
6200	6181	855	8381	428
6400	6381	882	8653	442
6600	6581	910	8924	455
6800	6781	938	9195	469
7000	6981	965	9466	483
7200	7179	993	9735	497
7400	7376	1020	10002	511
7600	7574	1047	10270	524
7800	7772	1075	10539	538
8000	7970	1102	10807	552
8200	8169	1130	11077	566
8400	8369	1157	11348	580
8600	8568	1185	11618	593
8800	8768	1213	11889	607
9000	8968	1240	12161	621
9200	9166	1268	12429	635
9400	9364	1295	12698	649
9600	9562	1322	12966	662
9800	9760	1350	13235	676
10000	9958	1377	13503	690

12420 TEXACO ROAD Houston, Texas 77013 713-453-6677 www.hytortexas.com

This chart supercedes all prior version regarding this tool

08/02/2011